ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0719, W0717, W0700, W0648, W0672, W0767, W0688, W

Street Name
NA, 2nd Crs, Gear College

Significant Landmark
opp church road at gangamma gudi

Segment No.
11/C-W0719/S122921

Total Length (m)
691.35

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	27.42	77.540509	13.072235	77.540569	13.072476	W0520	W0518
2	156.68	77.539820	13.072385	77.541212	13.072005	W0611	W0027
3	122.71	77.550347	13.059399	77.551472	13.059278	W0765	W0065
4	182.24	77.550367	13.059222	77.549999	13.057614	I0246	W0765
5	71.22	77.547363	13.057818	77.547378	13.057175	W0700	W0719
6	131.08	77.546865	13.056907	77.547977	13.057372	M0005	I0721

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements and asphalting to mariyamma block main road and opp church road at gangamma gudi in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Divi

Sanctioned Estimated Amount (Rs.)
2500000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements and asphalting to mariyamma block main road and opp church road at gangamma gudi in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-15-000003

Work Order No.
EE/BTP/BBMP/E-PMT/35/2015-16

Work Order Date
22/04/2015

Period of Extention
60 DAYS

Defect Liability Period From
31/07/2015

Defect Liability Period To
30/07/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B B UMESHA		0.00

Phone No.	E-Mail ID
9886213563	

Field Inspection Details

Number of Trees	Any Other Information	Name
6		RANGANATH

Date of Inspection	Remarks
25/03/2017	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0719, W0717, W0700, W0648,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/03/2017	24/04/2017	COMPLETED
SE	VASU K M	25/03/2017	24/04/2017	COMPLETED
EE	VASU K M	25/03/2017	24/04/2017	COMPLETED
AEE	MAHADEV	25/03/2017	24/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0719, W0717, W0700, W0648,

AE	RANGANATH	25/03/2017	24/04/2017	COMPLETED
AE	RANGANATH	25/03/2017	24/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0719, W0717, W0700, W0648,